
Q1 What type of cast did you apply to the patient?






ANSWER CHOICES	RESPONSES	
Short Arm Cast	69.92%	172
Thumb Spica Cast	4.88%	12
Boxer Cast	2.03%	5
Long Arm Cast	10.57%	26
Short Leg Cast	9.35%	23
Long Leg Cast	1.22%	3
Other	2.03%	5
TOTAL		246

Q2 How old is the patient?


Answered: 249 Skipped: 3



	LESS THAN 8 YEARS OLD	8-13 YEARS OLD	14-20 YEARS OLD	21-35 YEARS OLD	36-64 YEARS OLD	65+ YEARS OLD	TOTAL	WEIGHTED AVERAGE
(no label)	23.29% 58	44.98% 112	14.86% 37	8.03% 20	6.43% 16	2.41% 6	249	2.37


Q3 How long did the patient wear the cast?






ANSWER CHOICES	RESPONSES	
One week or less	4.03%	10
2 weeks	23.39%	58
3 weeks	32.26%	80
4 weeks	31.05%	77
5 weeks	7.26%	18
6 weeks	2.02%	5
7 weeks +	0.00%	0
TOTAL		248

Q4 What was the condition of the patient's skin at the cast removal stage?




	EXCELLENT	GOOD	AVERAGE	POOR	TOTAL	WEIGHTED AVERAGE	
(no label)	45.20% 113	39.60% 99	12.40% 31	2.80% 7	250		1.73

Q5 What was the condition of the AquaCast padding at the cast removal stage?



	EXCELLENT	GOOD	AVERAGE	POOR	TOTAL	WEIGHTED AVERAGE	
(no label)	37.50% 93	41.94% 104	16.53% 41	4.03% 10	248		1.87


Q6 Did you have any unscheduled cast changes with this cast?



ANSWER CHOICES	RESPONSES	
Yes	6.02%	15
No	93.98%	234
TOTAL		249


Q7 If yes, to Question 6, what was the reason?

Answered: 14 Skipped: 238




ANSWER CHOICES	RESPONSES	
Patient damaged cast	7.14%	1
Patient complained of pain or swelling	7.14%	1
Skin issue	7.14%	1
Fiberglass broke down	21.43%	3
AquaCast padding broke down	0.00%	0
Other	0.00%	0
Other (please specify)	57.14%	8
TOTAL		14

Q8 Did your patient appreciate the flexibility of having a waterproof cast?



ANSWER CHOICES	RESPONSES	
Yes	95.98%	239
No	4.02%	10
TOTAL		249

Q9 Based on your experience, would you recommend AquaCast to your co-workers and/or to patients?



ANSWER CHOICES	RESPONSES	
Yes	93.09%	229
No	6.91%	17
TOTAL		246